

QUALITY CERTIFICATE

binder of the state of the stat	Sandrada Sandrada (Sandrada California)				
Vessel	Sample & Analysis	Port	Providence, R.I.	Report	080606
Customer	Sprague Providence	Date	August 21, 2006	Reference	
Operation	Analysis	Terminal	Sprague Providence	Sample #	868139

Name of material being tested Description of sample source Samples Drawn by (company) Samples Tested by (company)

No 6 Fuel Oil

Shore Tank #6 After Discharge Inspectorate Inspectorate

Tests being Performed	Test method	Sample Resu	ults
Gravity API @ 60F / Denisty Flash Point, PMCC, F Viscosity cSt @ 122F Viscosity SSF @ 122F Pour Point C / F Sulfur , Wt% Water and Sediment, Vol % Sediment by Extraction, wt% Water by Distillation, Vol% Gross Heat of Combustion, BTU / Ib Gross Heat of Combustion, BTU / gal Ash, wt % Vanadium, ppm Sodium, ppm Nitrogen, wt% Ashphaltenes, wt% Conradson Carbon Residue	D - 4052 D - 93 D - 445 D - 2161 D - 97 D - 4294 D - 1796 D - 473 D - 95 D - 240 D - 240 D - 482 D - 5863B D - 5762 IP - 143 D - 189	11.4 / 209 293.9 138.8 0 / 32 0.856 0.05 0.95 <0.1 18,420 151,781 0.05 30 17 0.398 1.05 3.71	0.9899
SPRAGUE PROVIDES THE ATTACHED INSPECTION REPORT/, REPRESENTING THE SPECIFICATIONS OF THE PRODUCT AT TERMINAL IN TANK ON THE DATE OF INSPECTION NOTED OF THIS ANALYSIS IS PROVIDED TO THE CUSTOMER FOR THE PESTABLISHING THE INDEPENDENTLY VERIFIED PRODUCT SPACEORY OF THE BASIS IN SPRAGUE'S TERMINAL SHORE TANK CERTIFICATE. THE INSPECTION REPORT IS NOT TO BE USED PURPOSE. SPRAGUE DISCLAIMS ANY LIABILITY FOR THE PROBY SPRAGUE TO CUSTOMER. SPRAGUE DISCLAIMS ANY WAF MERCHANTABILITY OR FITNESS FOR AN INTENDED USE EXCEPT A SET FORTH IN WRITING IN ANY CONTRACT OR TERMS OF SAI AND A BUYER OF PRODUCT. SPRAGUE ASSUMES NO LIABILITY THAT MAY ARISE FROM CUSTOMER'S USE OF THIS INSPECTION.	THE SPRAGUE N THE CERTIFICATE, URPOSE OF PECIFICATION ON AS NOTEO ON THE POR ANY OTHER DOUCT AFTER DELIVERY RANTY OF SMAY BE SPECIFICALLY LE BETWEEN SPRAGUE		
#REF!	#REF!		#REF #REF #REF

^{**} Annotates Analysis Contracted Out

Michael White

^{***} Annotates Loadport information- this test was not performed by Inspectorate